



**Steel Construction Certification Scheme Limited**  
4 Whitehall Court, Westminster, London SW1A 2ES  
Tel: +44 (0) 20 7839 3980  
Fax: +44 (0) 20 7747 8199  
Email: [sccs@steelconstruction.org](mailto:sccs@steelconstruction.org)  
[www.steelconstruction.org](http://www.steelconstruction.org)

## EC Certificate of Factory Production Control (FPC) 2273 – CPR – 0344

In compliance with Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011  
(the Construction Products Regulation or CPR)  
it has been stated that the construction product:

### Structural Components for Steel Structures

Harmonised	Type / Execution Class of the Construction Product	Declaration Method
BS EN 1090-1: 2009 + A1:2011	Load bearing and welded structural steel components up to EXC 2 according to BS EN 1090-2:2008+A1:2011	1, 2, 3a and 3b table A.1 of BS EN 1090-1: 2009 + A1:2011

placed on the market by  
**Castle Welding & Fabrication Ltd**

and produced in the factory(ies)  
Sabre Engineering Works, West Pennard, Glastonbury, Somerset, BA6 8ND

is submitted by the manufacturer to the initial type-testing of the product, a factory production control and to the further testing of samples taken at the factory in accordance with a prescribed test plan and that the notified body No. 2273 – Steel Construction Certification Scheme Ltd - has performed the initial inspection of the factory and of the factory production control and performs the continuous surveillance, assessment and approval of the factory production control.

**Attestation** This certificate attests that all provisions concerning the attestation of factory production control described in Annex ZA of the standard:  
**BS EN 1090-1: 2009 + A1:2011** were applied.

**Date of first issue** **October 2014**

**Date of this issue** **3 October 2014**

**Date of next Surveillance** **by 2 October 2015**

**Validity Period** This certificate remains valid as long as the conditions laid down in the harmonised standard in reference or the manufacturing conditions in the factory or the FPC itself are not modified significantly.

**Chairman:**  
D Woodward

**Scheme Manager:**  
S Blackman